Introduction GDS Delivery Version: D3.2.0 ☐ Full Delivery ☐ Partial ICA #: 10374			
In Flight Spacecraft: MGS M98 Orbiter M98 Lander Stardust Other []			
Pre_Flight Spacecraft:			
Type:			
Notice: Times Below were decided at the Change Board.			
Installation Window: Best Times to Install: Freeze Times:			
MCR's 522 - MPL TCM Block Change for ISA Z49353 ISA's			
Z49353 - Acquisition of signal immediately after spacecraft separation indicated symptoms of a failure to acquire inertial reference. Absence of valid star camera images indicate the possibility of a hardware anomaly. Contingency plan M98-SCT-CP-0401 was executed.			
2. Delivery Location: mgcm1:/staging/MSOP/seq			
3. SEQ Workstations - Installation Instructions: ☐ N/A ☐ (See Attached - Directory Listing)			
a) Special Alerts - Before Install			
☐ ASP - Must be Stopped - Coordinate with SEQ Team Chief and SIE on Duty			
☑ Notify S/W Dev: ☑ J. Morris (4-1069) ☑ S. Wissler (4-0153) & ☑ SIE on Duty			
Comments:			
b) Install - Tar file: D3.2.0-SEQ-000-SEQ tar in directory: /msop/seq/			
On: PST workstations			
 copy the tarfile: D3.2.0-SEQ-000-SEQ.tar - to subdirectory: /msop tar -xvf D3.2.0-SEQ-000-SEQ.tar rm D3.2.0-SEQ-000-SEQ.tar 			
Comments:			

Date: 14 Oct 99

MSOP PSS Configuration for D3.2.0-SEQ-000-SEQ.tar

c) Notify: ⊠ J. Morris (4-1069) ⊠ S. Wissler (4-0153) □Linda Lee (3-9568), when Install is completed.
 Software Dev will configure /msop/seq_data and other areas
2) Software Dev will Notify: \boxtimes SIE on Duty \boxtimes CM when configuration is completed.
3) SIE on Duty SEQ Team Chief Software Development will:
Restart ASP Notify - ACE, so Operations may continue Notify - CM
Special - User's - Alerts - After Install:
 ✓ Log off workstation - then Log back on (files need to be re-configured) ✓ Incon's MUST be updated ✓ Previous symout can be used ✓ Default - symout MUST be used
Comments:
4. SCT Workstations - Installation Instructions: (See Attached - Directory Listing)
a) Special Alerts - Before Install
 copy the tarfile: D3.2.0-SEQ-000-SEQ.tar - to subdirectory: /msop tar -xvf D3.2.0-SEQ-000-SEQ.tar rm D3.2.0-SEQ-000-SEQ.tar
Comments:
b) Install Tar file: D3.2.0-SEQ-000-SEQ.tar in /msop/seq
On:
Comments:
c) Notify:
 Software Dev will configure /msop/seq_data and other areas ☐ clean-out /engineering ☐ verify software installed correctly ☐ run test cases
2) Software Dev will Notify: ACE CM - when configuration is completed.
Special - User's - Alerts - After Install:
□ Log off workstation - then Log back on (files need to be re-configured)
Comments:

This form will be placed on our homepage, in the following URL: http://mgsw3.jpl.nasa.gov/seq/seq_dev/

Directory Listing: D3.2.0-SEQ-000-SEQ.tar

2235 Oct 13 18:15 1999 seq/bin/mpl-seq-adapt-setup

417738 Oct 13 18:37 1999 seq/satf/M98.lander.B77a.satf

Sequence Development Tests - ran on: mdevttacs & mtbseq1

Script run_local_SIM_rtc_ASP_tests (Ran on mdevttacs & mtbseq1 – runs ASP locally)

Options Selected		Comments
<u>X</u>	1 - file_load tests (ic - ifl) 8-tests	
<u>X</u>	2 - SCT - ic & ec - tests - 13-tests - sdu-mgs-mco-mpl	Tests ran as expected, everything, ran
	3 - MAG - nipc tests - 2-tests - mgs only	through the ASP
	4- All tests	_

Script: run_block_tests (Each block is run through Seggen)

Ran – MPL - test and - compares D3.2.0_mtbseq1 with D3.2.0_mdevttacs Ran – test and - compares D3.2.0_mdevttacs with D3.1.0_mtbseq1

	Options Selected	Comments
<u>X</u>	1 - mpl - Blocks	
	2 - mco - Blocks	Test ran as expected all miss-compares
	3 - mpl & mco - Blocks	were explained, due to block updates
	4 - sdu - Blocks	
	5 - All tests	